

# DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

Complete:\_\_ Exploration: Partial: X Inspection Date & Time: 2/9/00 9:30 to 2:30 Date of Last Inspection: 1/20/00

Division Director 801-538-7223 (TDD)

Mine Name: Des Bee Dove County: Emery Permit Number: ACT/015/017 Permittee and/or Operator's Name: PacifiCorp/Energy West Mining Company.

Business Address Box 1008, Huntington, Utah 84528

Type of Mining Activity: Underground X Surface Prep. Plant Other

State Officials(s): Susan White and Wayne Western

Company Official(s): Dennis Oakley

Federal Official(s):\_\_\_\_

Weather Conditions: Fair and cool

Existing Acreage: Permitted- 2760 Disturbed- 24 Regraded- Seeded- Bonded- 24 Increased/Decreased: Permitted-0 Disturbed-0 Regraded-0 Seeded-0 Bonded-0

Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (\_Phase I/\_Phase II/\_Final Bond Release/ Liability\_Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	<u>[X]</u>	$\Box$	[X]	
3.	TOPSOIL			$\Box$	$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	$\Box$	[ <u>X</u> ]	
Ъ.	SEDIMENT PONDS AND IMPOUNDMENTS	$\Box$	$\Box$		$\Box$
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	. []
d.	WATER MONITORING	$\Box$	$\Box$	П	
e.	EFFLUENT LIMITATIONS				Ц
5.	EXPLOSIVES		П	. [_]	Ц
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				Ц
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		$\Box$		
8.	NONCOAL WASTE	[X]	$\Box$	[X]	$\Box$
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES		П	Ц	Ц
10.	SLIDES AND OTHER DAMAGE			Ц	
11.	CONTEMPORANEOUS RECLAMATION		П		Ц
12.	BACKFILLING AND GRADING			Ц	
13.	REVEGETATION		Ц		Ħ
14.	SUBSIDENCE CONTROL			Ц	Ц
15.	CESSATION OF OPERATIONS				$\Box$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING			· <u> </u>	
b.	DRAINAGE CONTROLS	[X]	- <u>[</u> ]	[X]	П
17.	OTHER TRANSPORTATION FACILITIES			<u> </u>	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	Ц	[X]	Ц
19.	AVS CHECK (4th Quarter-April, May, June)_(date)		П	Ц	Ц
20.	AIR QUALITY PERMIT		П	Ц	Ц
21.	BONDING & INSURANCE		$\Box$	$\sqcup$	П

PERMIT NUMBER: ACT/015/017

DATE OF INSPECTION: 2/9/00

## (Comments are Numbered to Correspond with Topics Listed Above)

#### 2. Signs and Markers

The permit entry sign near the gate along the main mine road requires replacing. The sign is no longer readable because of shot gun holes. The new sign should be placed along the road at the cattle gaurd which is the point of entry to the permit area.

#### 4. Hydrologic Balance

- **a.** Diversions The diversion collecting road runoff below the gate needs to be reestablished. No surface drainage map for the facilities area could be found in the permit. Plate 3-8, Surface Drainage Map (sheet 1 of 2) appears to be missing from the permit.
- **c.** Other Sediment Control Measures Berms around the recently demolished pump house need to be improved.

#### 8. Noncoal waste

A general clean-up of the site is required. Noncoal waste was observed within the permit and disturbed area from removal of the waterlines and electric lines. The trash below the tipple pad around the half round culvert had not been cleaned. Mr. Oakley stated they couldn't access the trash because the snow had just melted on this steep slope.

## 18. Support Facilities/Utility Installations

The water and electric lines have mostly been removed. Several poles and insulation from the water line still needs to be removed.

Copy of this Report:

Mailed to: James Fulton (OSM), Chuck Semborski (PacifiCorp)

Given to: Pamela Grubaugh-Littig (DOGM)

Inspector's Signature: Justin M. White #35 Date: February 10, 2000